

UltraTape



Reinraum-Klebeband PE Surface-Protection Sterile

#1314-2

pure¹¹-Nr. : 1130051 , Marke : UltraTape

Eigenschaften

- Steril
- Marke: UltraTape
- Breite in cm: 5 cm
- Chemikalienbeständigkeit
- Klebestärke: stark
- Klebstoff: Acryl
- Polyethylen: 100 %
- Reinheitsgrad: Ultrac Clean
- Rückstandsfrei ablösbar
- Temperaturbeständig
- Wasserbeständig

Empfohlene Reinraumklassen

ISO 4 | 5 | 6 | 7 | 8 | 9

GMP A/B | C | D



Material

-

Verpackung

- 24STK

pure¹¹ GmbH

Bavariafilmplatz 7 | D-82031 Grünwald

Geschäftsführer: Julian Kropp

AG München HRB 171307

T +49 89 5589434 0

F +49 89 5589434 77

www.pure11.de

info@pure11.de

Produktvarianten

pure¹¹-Nr.: 1130051TP2I, Reinraum-Klebeband PE Surface-Protection Sterile #1314-2

Steril; Farbe: Transparent; Breite: 2" / VE: 24STK

pure¹¹ GmbH

Bavariafilmpfad 7 | D-82031 Grünwald

Geschäftsführer: Julian Kropp

AG München HRB 171307

T +49 89 5589434 0

F +49 89 5589434 77

www.pure11.de

info@pure11.de

UT1314 Polyethylene Low Adhesion Surface Protection Cleanroom Tape

DESCRIPTION

UltraTape 1314/ 0314 cleanroom tape is a low adhesion temporary protection tape designed for a variety of surface protection applications including metal, plastic, and painted surfaces.

- Low Tack surface protection against dust, dirt and moderate abrasion
- Stable adhesion levels resulting in good removability
- Clean removal
- Cleanroom certified

PROPERTIES

Backing	Polyethylene
Adhesive	Acrylic
Total Thickness	3.0 mils / 0.08 mm
Elongation	450%
Adhesion to Stainless Steel	11.0 oz/in (3.02 N/25 mm)
Release Liner	N/A
Operating Temperature	-40°F to 190°F (-40°C to 88°C)
Tensile Strength	2500 PSI
Length	250 ft.
Colors	Clear (CL)

To achieve ultimate adhesion, the bonding surface should be clean, dry, and free of dirt and oils. The strength of the adhesive bond is dependent on the amount of surface area directly in contact with the adhesive. Firm pressure is recommended to achieve good adhesive to surface contact.

UltraTape recommends that each user conduct their own test to determine the product's suitability for the intended application and shall assume all risks and liabilities in connection therewith. Materials should be stored at 70°F (21°C) with 50% relative humidity.